



BROKERAGE | CHARTER | BERTHS | FINANCE | INSURANCE | YACHT MANAGEMENT

#### **BROKER'S COMMENTS**

This Dutch-designed and built Doggersbank 1400 MY is well maintained by it's current (2nd) owner. Although Doggersbank is already known as a sturdy, and seaworthy yacht, "Bien Mérité" has some extra renewings like new navigation equipment, generator and Kabola-heating. With these renewings and with her double glazed windows, she's is also ready to use for longer stays on board. She's equipped with 2 cabins and a convertible dinette to accommodate 6. The Doggersbank 1400 MY is located at our sales office on shore in Sint Annaland.

Joris van de Rijt

#### **SPECIFICATIONS**

Dimensions	14.95 x 4.40 x 1.30 (m)	Builder	Doggersbank jachtbouw Woudsend
Built	1986	Cabins	2
Material	Steel	Berths	6
Engine(s)	1 x Volvo Penta MD70C diesel	Hp/Kw	145.00 (hp), 106.72 (kw)
Asking price	sold (VAT)	Lying	at sales office

#### CONTACT

Sales office	De Valk Sint Annaland B.V.	<b>Telephone</b> +31 (0)166 601 000	
Address	Koelhuisweg 4	E-mail sintannaland@devalk.nl	
	4697 RM Sint Annaland		
	NL		

#### **DISCLAIMER**

These particulars are given in good faith as supplied but cannot be guaranteed.



#### **GENERAL**

Model DOGGERSBANK 1400 MY

**Type** motor yacht

LOA (m) 14,95 LWL (m) 13,15 Beam (m) 4,40 Draft (m) 1,30 Air draft (m) 8,70 Air draft min (m) 3,40 Headroom (m) 1,91 Year built 1986

Builder Doggersbank jachtbouw Woudsend

**Country** The Netherlands

**Designer** Vripack Yachting Sneek

Displacement (t) 19
Hull material steel
Hull colour blue

Hull shaperound-bilgedSuperstructure materialaluminiumRubbing strakestainless steel

Deck material steel

Deck finish teak (new 2009)

Superstructure deck finish teak
Antifouling (year) 2022
Window frame aluminium

Window material double glazing (new 2018)

**Deckhatch** yes

**Insulation** glasswool

Steadying sail with mastCan be loweredFuel tank (litre)steel 2400Level indicator (fuel tank)Gauge glass



Freshwater tank (litre) stainless steel 1000

Level indicator (freshwater) Defect

Blackwater tank (litre) polyethylene
Level indicator (blackwater) Not connected

Blackwater tank extraction deck extraction + pump

Wheel steering hydraulic

Outside helm position hydraulic

More info on hull Underwaterbody new epoxy primer in 2008

More info on paintworkHull painted in 2015 with AwlgripExtra infoSuperstructure re-painted in 2008

Extra info

Woodwork exterior re-varnished in 2021

Extra info

Air draft (m) with sprayhood up: 3,61

#### **ACCOMMODATION**

Cabins 2
Berths 6
Interior teak

Floor carpet + wood print

Aft deck With 3 big lockers

Saloon yes Headroom saloon (m) 1,91

**Heating** central hot water Kabola (new circa 2019)

Navigation centeryesChart tableyesAft Cabinyes

Dinette to convert into berth Near galley

Galley Modified in 2008

**Countertop** plastic

Sink stainless steel

Cookercalor gas Zanussi (2009)OvenBosch Gourmet 2000



Fridge 2x (2009)
Freezer In fridge

Hot water system 220V/engine/heating

Water pressure system electrical
Crockery yes

Owners cabin French bed (new matrrasses 2021)

Bed length (m) 2,00 x 1,60

Wardrobe hanging/drawers/shelves

Bathroomen suiteToileten suiteToilet systemelectric

Wash basin in the bathroom

Shower en suite

Guest cabin 1 twin single

Bed length (m) 1,95 x 0,65

Wardrobe hanging and shelves

Toilet en suite

Toilet system electric

Wash basin at the toilet

#### **MACHINERY**

No of engines 1

Make Volvo Penta Type MD70C HP 145 kW 106.72 Fuel diesel Year installed 1986 Maximum speed (kn) 8 Cruising speed (kn) Consumption (I/hr) 12



Engine hours 6085

Engine cooling system freshwater heat exchanger

**Drive** shaft

Engine controls bowden cable

**Gearbox** hydraulic

Secondary engine diesel Volvo Penta D2-40 (new 2015) for emergency

Engine controls bowden cable

Bowthruster hydraulic

Propeller type fixed + folding for Volvo Penta D2-40

Propeller blades 3 (main engine) + 2 (emergency engine)

Shaft lubricationoilbathManual bilge pumpyesElectric bilge pump3x

Electrical installation 12V / 24V / 230V

Generator Nanni GMS 7,5 kW (new 2015)

Running hours generator 295

 Start battery
 2x 230 Ah (2021)

 Service battery
 4x 230 Ah (2021)

Generator battery 1x (2017)

Battery monitor Mastervolt Easyview 5

Battery charger Seperate 12V charger for generator battery

Battery charger/inverter Mastervolt mass combi ultra 24/3500-100

Shorepower with cable

Insulation transformer Mastervolt (defect)

Stabilizers Koop Nautic TwinChannel with fins under swimming platform

Extra info Watertight door to engine room

**NAVIGATION** 

Electric compass Via autopilot

Depth sounder/logSimrad inside + outside (new 2020)WindsetSimrad inside + outside (new 2020)



VHF Simrad HS90 (new 2020)
VHF handheld Simrad HS35 (new 2020)
Autopilot Simrad AP44 (new 2020)

Rudder angle indicator On autopilot

Radar Simrad HALO24 (new 2020)

Radar/plotter Simrad NSS Evo3 7 & 9 inch (new 2020)

Navtex ICS Nav 6

Electronis chart(s) yes

AIS transponder Simrad Nais 500 (new 2020)

Navigation lights yes Searchlight yes

#### **EQUIPMENT**

Fixed windscreen yes

Sprayhood (new 2019)

Bathing platform yes

Boarding ladder stainless steel

Transom door yes
Gangway yes
Anchor Delta
Anchor chain 30 meter
Windlass electrical

Deck wash On swimming platform (pump defect)

Davits stainless steel Simpson Serie 7 (new circa 2015, needs repair)

Davits controls electrical

Sea railing stainless steel

Grab rail (superstructure) teak
Railing side opening gates 2x

Pulpit Needs to be straightened

Life raft (pers) container 4 (new circa 2015)

**Lifejackets** yes



**Lifebuoy** yes

Wiper 3x inside + 2x outside

HornyesFendersyesMooring linesyesSpare partsyesToolsyes

Alarm system E-marine

Radio-cd player yes
Speakers in salon yes
Clock - barometer yes

Fire extinguisher 2x (needs service / replacement)

**RIGGING** 

**Staysail** yes



































































































































