



BROKERAGE | CHARTER | BERTHS | FINANCE | INSURANCE | YACHT MANAGEMENT

#### **BROKER'S COMMENTS**

This well maintained round bilged Stevenvlet 1080 has a very practical and spacious layout which will make longer stays onboard very comfortable. With her strong engine, bowthruster and easy deck access through the 2 side doors this Stevenvlet is easy to handle. She just had a new paintjob on the under water body, hull, decks, superstructure and is now ready for a visit with us in Sint Annaland.

Joris van de Rijt

### **SPECIFICATIONS**

Dimensions	10.80 x 3.95 x 0.90 (m)	Builder	Steven
Built	1988	Cabins	1
Material	Steel	Berths	2
Engine(s)	1 x VM Motori 27B/3 diesel	Hp/Kw	81.00 (hp), 59.62 (kw)
Asking price	sold (VAT )	Lying	at sales office

#### CONTACT

Sales office	De Valk Sint Annaland B.V.	Telephone	+31 (0)166 601 000
Address	Koelhuisweg 4	E-mail	sintannaland@devalk.nl
	4697 RM Sint Annaland		
	NL		

#### **DISCLAIMER**

These particulars are given in good faith as supplied but cannot be guaranteed.



### **GENERAL**

Model STEVENVLET 1080

**Type** motor yacht

 LOA (m)
 10,80

 Beam (m)
 3,95

 Draft (m)
 0,90

 Air draft (m)
 3,77

 Air draft min (m)
 2,76

 Headroom (m)
 1,90

Year built 1988
Builder Steven

**Country** The Netherlands

Displacement (t) 13
CE norm NA
Hull material steel

Hull colour blue (painted in 2023)

Hull shape hard chine
Superstructure material steel

Rubbing strake rubber (remounted in 2023 during paintjob)

Deck material steel

Deck finishnon-skid paint (painted in 2023)Superstructure deck finishnon-skid paint (painted in 2023)Cockpit deck finishnon-skid paint (painted in 2023)

Antifouling (year) 2023

Window frame aluminium (remounted in 2023 during paintjob)

Window material tempered glass

**Deckhatch** 2 x Gebo

**Insulation** Superstructure

Fuel tank (litre) yes

Level indicator (fuel tank) Not working

Freshwater tank (litre) yes

Level indicator (freshwater)

Wheel steering

hydraulic

Inside helm position yes

More info on paintwork Hull/superstructure painted: De IJssel DC 2 Components in 2023

Extra info Air draft ca. 2,76 m with mast down

Extra infoExtra infoOwner invested approx. € 25,000 in boat (winter 2022/2023)Extra infoCooling water temperature gauge not indicating correctly

### **ACCOMMODATION**

Cabins 1 Berths 2 Interior teak Floor wood Pilot house/deck saloon yes Saloon yes Headroom saloon (m) 1,90 Sliding roof manual

**Heating** diesel ducted hot air Webasto

DinetteyesOpening door to cockpityesGalleyyesCountertopwood

Sinkstainless steelCookercalor gas 3 burner

Fridge 1 x Isotherm + 1 x Electrolux. \*Electrolux fridge is defective

Hot water system 220V + engine

Water pressure system electrical (small defect, sucking air)

Owners cabin twin single V-Bed

Bed length (m) 2 beds 1,90 x 0,80

Wardrobe hanging and shelves

**Bathroom** en suite



Toilet en suite
Toilet system manual

Wash basin in the bathroom

Shower en suite

### **MACHINERY**

No of engines

 Make
 VM Motori

 Type
 27B/3

 HP
 81

 kW
 59.62

 Fuel
 diesel

 Year installed
 1999

 Engine hours
 1519

Engine cooling system closed keelcooling

**Drive** shaft

Engine controlsbowden cableGearboxhydraulicBowthrusterelectricExhaustdryPropeller typefixedPropeller blades4

Shaft lubricationgreaseElectrical installation24V/230V

Batteries 4 x
Battery monitor Victron
Battery charger Victron

Inverter Victron 24 V / 2000 W

Solar panel2 x on roofShorepowerwith cable



#### **NAVIGATION**

Depth sounderClipperVHFShipmate

Rudder angle indicator yes

GPS Furuno GP-32

Navigation lights yes

#### **EQUIPMENT**

Cockpit cover 1 x winter cover + 1 x summer cover

Cockpit cushions yes

Boarding ladder stainless steel

Anchor Pool
Anchor chain yes

Windlass mechanical Lofrans royal RY001477

Capstan On windlass

Sea railing stainless steel (remounted in 2023 during paintjob)

Grab rail (superstructure) stainless steel

Railing side opening gates 2 x

Wiper 2 x (port side not working)

HornelectricFendersyesMooring linesyes

TV Samsung

Radio-cd player yes
Speakers in salon yes
Clock - barometer yes
Fire extinguisher yes































































































































