



DE VALK  
YACHT BROKERS



MASON 53



DE VALK  
YACHT BROKERS

## BROKER'S COMMENTS

This 53' Mason is a dream boat with traditional lines, a solid structure, and amazing space. She sails beautifully and has a lovely interior. Recently upgraded (2024) with new canvas (sail bags, bimini, dodgers, sun cover), interior cushions, fresh deck paint, varnished woodwork (10 layers), and a 5-layer copper-coated bottom (2022). Perkins Engine and Northern Light Genset serviced (2024). A true-Blue Water cruiser with extensive inventory, perfect for living aboard and cruising the region. Ready to sail away, offers invited.

*Jeroen Kool*

## SPECIFICATIONS

<b>Dimensions</b>	16.31 x 4.52 x 2.09 (m)	<b>Builder</b>	Ta Shing Yacht Building
<b>Built</b>	1984	<b>Cabins</b>	4
<b>Material</b>	GRP	<b>Berths</b>	9
<b>Engine(s)</b>	1 x Perkins 4.236 diesel	<b>Hp/Kw</b>	85.00 (hp), 62.56 (kw)
<b>Asking price</b>	Under Offer (VAT )	<b>Lying</b>	Singapore

## CONTACT

<b>Sales office</b>	De Valk Asia	<b>Telephone</b>	0601114078055
<b>Address</b>		<b>E-mail</b>	asia@devalk.nl
	AS		

## DISCLAIMER

These particulars are given in good faith as supplied but cannot be guaranteed.



## GENERAL

<b>Model</b>	MASON 53
<b>Type</b>	sailing yacht
<b>LOA (m)</b>	16,31
<b>LWL (m)</b>	12,12
<b>Beam (m)</b>	4,52
<b>Draft (m)</b>	2,09
<b>Headroom (m)</b>	2,00
<b>Year built</b>	1984
<b>Launched</b>	1984
<b>Builder</b>	Ta Shing Yacht Building
<b>Country</b>	Taiwan
<b>Designer</b>	A Mason
<b>Displacement (t)</b>	17,5
<b>Ballast (tonnes)</b>	6,5
<b>CE norm</b>	A
<b>Hull material</b>	GRP
<b>Hull colour</b>	white
<b>Hull shape</b>	S-bilged
<b>Keel type</b>	long keel
<b>Superstructure material</b>	GRP
<b>Rubbing strake</b>	wood
<b>Deck material</b>	wood epoxy
<b>Deck finish</b>	non-skid moulded in
<b>Superstructure deck finish</b>	non-skid moulded in
<b>Cockpit deck finish</b>	teak
<b>Antifouling (year)</b>	2022, copper coat 5 layers
<b>Dorades</b>	4 Yes
<b>Window frame</b>	stainless steel
<b>Window material</b>	tempered glass
<b>Deckhatch</b>	yes



<b>Portholes</b>	stainless steel
<b>Insulation</b>	foam
<b>Radar arch</b>	non collapsible
<b>Fuel tank (litre)</b>	steel 2x 400
<b>Level indicator (fuel tank)</b>	Display at nav station
<b>Fuel daytank (litre)</b>	steel 2x 200
<b>Level indicator (daytank)</b>	Display at nav station
<b>Freshwater tank (litre)</b>	stainless steel 2x 300
<b>Blackwater tank (litre)</b>	polyethylene
<b>Blackwater tank extraction</b>	deck extraction + pump
<b>Wheel steering</b>	cable steering
<b>Outside helm position</b>	cable steering
<b>Emergency tiller</b>	yes
<b>More info on paintwork</b>	Deck painted 2023
<b>Extra info</b>	There is a soft spot in a small section of the port side deck above the pantry. The port light has been re-sealed, and restoration of this spot is recommended.

## ACCOMMODATION

<b>Cabins</b>	4
<b>Berths</b>	9
<b>Interior</b>	teak
<b>Floor</b>	teak
<b>Open cockpit</b>	yes
<b>Saloon</b>	yes
<b>Headroom saloon (m)</b>	2,0m
<b>Sliding roof</b>	manual
<b>Heating</b>	electric 220V
<b>Heating 2</b>	electric 220V
<b>Air-conditioning</b>	reverse cycle airco 3x
<b>Navigation center</b>	yes
<b>Chart table</b>	yes



Aft Cabin	yes
Dining room	yes
Dinette	yes
Dinette to convert into berth	yes
Opening door to cockpit	yes
Galley	yes
Countertop	wood
Sink	stainless steel
Cooker	calor gas 4 burners
Oven	yes
Gas alarm	yes
Microwave	yes
Fridge	Frigoboat Paris 35F, 60 L
Freezer	Frigoboat Capri 50F, 50 L
Hot water system	220V
Water pressure system	electrical
Kettle	yes
Coffee maker	yes
Owners cabin	double bed + single bed
Bed length (m)	2m
Wardrobe	hanging/drawers/shelves
Bathroom	en suite
Toilet	en suite
Toilet system	electric
Wash basin	at the toilet
Shower	en suite
Guest cabin 1	v-bed
Bed length (m)	2m
Wardrobe	hanging/drawers/shelves
Bathroom	shared
Toilet	shared
Toilet system	electric



Wash basin	at the toilet
Shower	shared
Guest cabin 2	bunk bed
Bed length (m)	2m
Wardrobe	hanging/drawers/shelves
Bathroom	shared
Toilet	shared
Toilet system	electric
Wash basin	at the toilet
Shower	shared
Guest cabin 3	bunk bed
Bed length (m)	2m
Wardrobe	hanging/drawers/shelves
Bathroom	yes
Toilet	shared
Toilet system	electric
Wash basin	at the toilet
Shower	shared
Extra info	Condensation from the aircon has impacted the lower bilge bulkhead beneath the floor and would benefit from maintenance.

## MACHINERY

No of engines	1
Make	Perkins
Type	4.236
HP	85
kW	62.56
Fuel	diesel
Year installed	1999
Maximum speed (kn)	9
Cruising speed (kn)	7,5



Consumption (l/hr)	5
Engine cooling system	seawater
Drive	shaft
Engine controls	bowden cable
Gearbox	hydraulic
Bowthruster	electric DE-Power SE 120/215T
Exhaust	watercooled
Propeller type	feathering
Propeller blades	3
Propeller shaft material	stainless steel
Shaft lubrication	water
Manual bilge pump	1
Electric bilge pump	2
Generator	wet exhaust Northern Lights 9,4 kW
Running hours generator	827
Start battery	Neutron Power Heavy Duty, 12v, 180AH 2024
Service battery	4x Trojan AGM Deep Cycle 6v 370 AH
Navigation Battery	2X sm12-100ht Gel, 12v, 100AH 2023
Generator battery	AC Delco Heavy Duty 12v 150 AH
Bowthruster battery	2x 12v 100AH AC Delco 2021
Battery monitor	yes
Battery charger	Victron Centaur 60 Amp (2023)
Inverter	Pure Sine Wave 220V 3000 W (2023)
Solar panel	2x 150Watt
Shorepower	with cable
Watermaker	Aquagive 140l/h (2013)

## NAVIGATION

Compass	At helm station, Danforth
Electric compass	Raymarine Fluxgate
Depth sounder	Raymarine i50



<b>Log</b>	Raymarine ST60+
<b>Windset</b>	Raymarine i60
<b>VHF</b>	Raymarine 55
<b>VHF handheld</b>	yes
<b>Autopilot</b>	Raymarine S3 + Type 2 Hydraulic drive
<b>Rudder angle indicator</b>	Raymarine
<b>Radar</b>	Raymarine Digital 18"
<b>GPS</b>	Raymarine Raystar 125
<b>Radar/GPS/plotter</b>	Raymarine C120W
<b>Wifi antenna</b>	Wifi router
<b>AIS transceiver</b>	Raymarine AIS650
<b>Radio receiver</b>	Satcom Sailor 150 Fleetbroadband
<b>EPIRB</b>	McMurdo E5 Smartfind 406
<b>Navigation lights</b>	yes
<b>Searchlight</b>	yes

## EQUIPMENT

<b>Storm blinds</b>	New 2024
<b>Cockpit cover</b>	New 2024
<b>Dodger</b>	New 2024
<b>Bimini</b>	New 2024
<b>Sun awning</b>	New 2024
<b>Cockpit cushions</b>	yes
<b>Cockpit table</b>	yes
<b>Cockpit chairs</b>	yes
<b>Boarding ladder</b>	stainless steel
<b>Anchor</b>	Bruce 30 kg
<b>Anchor chain</b>	55m, 12mm, Mantus swivel (2023)
<b>Anchor 2</b>	Delta 25 kg
<b>Windlass</b>	electrical Lofrans 1700W/12V
<b>Capstan</b>	yes



Dinghy	rigid inflatable Highfield UL340 (2018)
Outboard	18 HP Tohatsu (2021)
Outboard support	yes
Davits	stainless steel
Davits controls	manual
Sea railing	wire
Grab rail (superstructure)	Teak, stainless steel
Railing side opening gates	yes
Pushpit	yes
Pulpit	yes
Life raft	container
Life raft (pers)	container 6 pax
Last life raft survey	2020
Lifejackets	8, 2x inflatable, 6x red type II
Lifebuoy	Lifelink sling white (2023)
Horn	electric
Radar reflector	yes
Fenders	4x F6
Mooring lines	yes
Spare parts	yes
Tools	yes
TV	Samsung 40", wall mount
Radio-cd player	yes
iPod connection	yes
Surround Sound System	yes
Cockpit speakers	yes
Speakers in salon	yes
Speakers in cabin	yes
Clock - barometer	yes
Fire extinguisher	5x ABC
Latest extinguisher survey	2023
Extinguisher in engine room	Vicinity



## RIGGING


<b>Rigging</b>	ketch
<b>Standing rigging</b>	wire 2016
<b>Brand mast</b>	Isomat
<b>Material mast</b>	aluminium
<b>Spreaders</b>	2
<b>Keel stepped mast</b>	yes
<b>Mainsail</b>	dacron 2014 Furled on boom
<b>Mainsail cover</b>	New
<b>Battcars</b>	yes
<b>Fully battened mainsail</b>	yes
<b>Mizzen</b>	dacron 2014 Furled on boom
<b>Mizzen sailcover</b>	New
<b>Genoa I</b>	darcon 2014
<b>Genoa furler</b>	yes
<b>A-symmetric spi</b>	Nylon 2014
<b>Staysail</b>	Dacron 2014
<b>Stormjib</b>	yes
<b>Reefing System</b>	main in-boom furling
<b>Backstay adjuster</b>	mechanical
<b>Boomvang</b>	tackle
<b>Primary sheet winch</b>	2x Lewmar 55, 1x electric
<b>Secondary sheet winch</b>	2x Lewmar 42, 1x Lewmar 40, 1x Arco 50
<b>Halyard winches</b>	2x Lewmar 42, 2x Lewmar 30, Mizzen 1x Lewmar 16
<b>Spinnaker winch</b>	yes
<b>Multifunctional winches</b>	halyard/sheet winches
<b>Spi-pole</b>	aluminium
<b>Extra info</b>	The mast step compartment sideboard has been affected by rainwater and requires fresh timber.











# MASON 53















# MASON 53








# MASON 53



# MASON 53



# MASON 53



# MASON 53



