

HALMATIC TALISMAN 49

DE VALK
YACHT BROKERS

BROKERAGE | CHARTER | BERTHS | FINANCE | INSURANCE | YACHT MANAGEMENT

HALMATIC TALISMAN 49

BROKER'S COMMENTS

Halmatic Talisman 49 "Flinter", this comfortable, fast and safe seagoing "Nelson style" motor yacht, is simply stunning in all respects! Spacious saloon, three cabins and 6 berths, accommodation for owners and guests are perfectly separated. Easy to handle by her two engines and bow/stern thrusters, perfectly maintained and ready to go. Follow our virtual tour; https://roundme.com/tour/236753/view/677403

Ger Bayens

SPECIFICATIONS

Dimensions	15.80 x 4.67 x 1.30 (m)	**Builder**	Halmatic/Scheepswerf Zevenhuizen
Built	1997	**Cabins**	3
Material	GRP	**Berths**	6
Engine(s)	2 x Caterpillar 3126 DI-TA diesel	**Hp/Kw**	2 x 420.00 (hp), 308.00 (kw)
Asking price	sold (VAT)	**Lying**	at sales office

CONTACT

Sales office	De Valk Sint Annaland B.V.	**Telephone**	+31 166 601 000
Address	Koelhuisweg 4	**E-mail**	sintannaland@devalk.nl
	4697 RM Sint Annaland		
	NL		

DISCLAIMER

These particulars are given in good faith as supplied but cannot be guaranteed.

HALMATIC TALISMAN 49

GENERAL

Model	HALMATIC TALISMAN 49
Type	motor yacht
LOA (m)	15,80
Beam (m)	4,67
Draft (m)	1,30
Headroom (m)	2,00
Year built	1997
Builder	Halmatic/Scheepswerf Zevenhuizen
Country	The Netherlands
Designer	Murray McCormack Associates
Displacement (t)	32
CE norm	NA
Hull material	GRP
Hull colour	blue
Hull shape	deep-V
Superstructure material	GRP
Rubbing strake	rubber
Deck material	GRP
Deck finish	teak
Superstructure deck finish	yes
Cockpit deck finish	teak
Antifouling (year)	2017
Dorades	yes
Window frame	aluminium
Window material	tempered glass
Deckhatch	3x
Portholes	yes
Flybridge	yes
Radar arch	collapsible RVS
Mast can be lowered	hydraulic

Fuel tank (litre)	3000 in 2 tanks
Level indicator (fuel tank)	yes
Freshwater tank (litre)	1200 in 2 tanks
Level indicator (freshwater)	yes
Blackwater tank (litre)	300 in 2 tanks
Wheel steering	hydraulic
Outside helm position	hydraulic
More info on hull	Van de Rest 2017
More info on paintwork	Hull 2010

ACCOMMODATION

Cabins	3
Berths	6
Interior	mahogany Upgraded in 2010
Floor	teak and holly
Aft deck	yes
Saloon	yes
Headroom saloon (m)	2,00
Heating	central heating Kabola
Air-conditioning	reverse cycle airco Owen
Navigation center	yes
Chart table	yes
Aft Cabin	yes
Dining room	yes
Dinette	yes
Sliding door to aft deck	yes
Galley	Refitted in 2010
Countertop	corian 2010
Sink	stainless steel 2x
Cooker	electric Siemens 4-Burner 2010
Extractor	Miele

Microwave/oven combi	AEG 2010 (KB9810E)
Fridge	2x BARCO 2010
Hot water system	220V + engine
Water pressure system	electrical
Owners cabin	French bed
Bed length (m)	2,15 x 1,80
Wardrobe	hanging/drawers/shelves
Bathroom	en suite
Toilet	en suite
Toilet system	electric 2010
Wash basin	in the bathroom
Shower	en suite
Guest cabin 1	v-bed
Bed length (m)	2,00 x 1,80
Wardrobe	hanging and drawers
Bathroom	shared
Toilet	shared
Toilet system	electric
Wash basin	at the toilet
Shower	shared
Guest cabin 2	bunk bed
Bed length (m)	1,98 x 0,70
Wardrobe	shelves
Bathroom	shared
Toilet	shared
Toilet system	electric
Wash basin	at the toilet
Extra info	Complete upholstery and cushions renewed (2010)

MACHINERY

No of engines	2

Make	Caterpillar
Type	3126 DI-TA
HP	420,00
kW	308,00
Fuel	diesel
Year installed	1997
Maximum speed (kn)	20,00
Cruising speed (kn)	15,00
Engine hours	5035
Engine cooling system	freshwater heat exchanger
Drive	shaft
Bowthruster	electric Vetus complete refit 2010
Sternthruster	electric Vetus
Gearbox	hydraulic
Exhaust	watercooled
Propeller type	fixed
Propeller shaft material	stainless steel
Shaft lubrication	water
Electric bilge pump	yes
Electrical installation	yes
Generator	Mastervolt Wisperpower 10 KVA 4-24v
Batteries	yes
Start battery	4X 2017
Battery monitor	Mastervolt
Battery charger	(2017)
Inverter	2 x
Battery charger/inverter	Mastervolt Mass Sine 24/1200
Shorepower	with cable
Trimtabs	yes

NAVIGATION

Compass	Plastimo
Electric compass	Raymarine ST60
Depth sounder	Raymarine ST60
Windset	Raymarine ST60
VHF	Shipmate RS8300 + AIS
VHF handheld	Icom IC-M71
Autopilot	Robertson AP-45
Radar/plotter	2x Raymarine E120
Navtex	Furuno NX-300
Searchlight	yes

EQUIPMENT

Sprayhood	yes
Cockpit cover	yes
Bathing platform	yes
Boarding ladder	stainless steel
Gangway	yes
Deck shower	yes
Anchor	yes
Anchor chain	yes
Windlass	electrical Vetus 1500W-24V
Dinghy	inflatable Zodiac Cadet 285
Outboard	Johnson 4 HP (2009)
Davits	stainless steel Simpson
Davits controls	manual
Sea railing	stainless steel
Grab rail (superstructure)	stainless steel
Railing side opening gates	yes
Life raft	container
Life raft (pers)	6
Last life raft survey	04-2016

Wiper	yes
Horn	
TV	LG
Radio-cd player	Panasonic SA-PMX5


DE VALK
YACHT BROKERS


DE VALK
YACHT BROKERS


DE VALK
YACHT BROKERS


DE VALK
YACHT BROKERS


DE VALK
YACHT BROKERS


DE VALK
YACHT BROKERS
Flinter


DE VALK
YACHT BROKERS
Flinter


DE VALK
YACHT BROKERS


DE VALK
YACHT BROKERS


DE VALK
YACHT BROKERS


DE VALK
YACHT BROKERS


DE VALK
YACHT BROKERS


DE VALK
YACHT BROKERS


DE VALK
YACHT BROKERS


DE VALK
YACHT BROKERS


DE VALK
YACHT BROKERS


DE VALK
YACHT BROKERS


DE VALK
YACHT BROKERS


DE VALK
YACHT BROKERS


DE VALK
YACHT BROKERS


DE VALK


VALK
BROKERS


DE VALK
YACHT BROKERS


DE VALK





DE VALK
YACHT BROKERS


VALK
BROKERS


DE VALK
YACHT BROKERS


DE VALK
YACHT BROKERS


DE VALK
YACHT BROKERS


DE VALK
YACHT BROKERS


DE VALK
YACHT BROKERS



DE VALK
YACHT BROKERS




DE VALK
YACHT BROKERS


DE VALK
YACHT BROKERS


DE VALK
YACHT BROKERS


DE VALK
YACHT BROKERS


DE VALK
YACHT BROKERS


DE VALK
YACHT BROKERS
FLINTER

Betreft: REFIT-overzicht

Tijdens de winterstalling 2009/2010 zijn de onderstaande werkzaamheden uitgevoerd aan boord van Halmatic Talisman 51 "Flinter" ter waarde van € 125.275 (inclusief BTW):

- Oliemonsters nemen
- Revisie n.a.v. analyse hoofdmotoren en generator
- Schroefassen trekken. Assen, glands en lagers inspecteren
- Inspectie stuurmachine
- Lenspompen inspecteren / vervangen
- Watermaker uitbouwen, huiddoorvoeren dichtmaken
- Afdichtingen hydrocilinders vervangen
- Hydrofoorpomp inspecteren / vervangen
- Motorsteunrubbers vervangen hoofdmotoren
- Verlichting opwaarderen
- Uitlaatslangen hoofdmotoren en generator vervangen
- Resonantie uitlaatslang SB achterhut verhelpen
- Brandstoftanks openen en schoonmaken
- Ca. 17m2 teakdek vlakken, kitnaden uitfrezen en opnieuw rubberen
- Antislip op salondak vervangen voor imitatie teak (kunststof)
- Antislip op salondak vervangen voor Afrozelia
- Ruitenwissers (Exalto) vervangen
- Witten vlak voor instrumentenpaneel tegen reflectie zonlicht
- 2e berghout 100x95 van ca. 2,5 mtr aanbrengen op de huid
- Anodes vervangen
- Antifouling aanbrengen onderwaterschip
- Borging relingtrap werkend maken
- Poetsen dek en opbouw

- Alle poorten vv nieuwe rubbers
- Verlichting opwaarderen
- Gehele elektrische installatie controleren
- Plaatsing tank 400 ltr extra drinkwater
- Aanpassing salontafel
- Hekschroef controleren
- Alle accu's testen
- Aanpassing salon stuurstand
- Vetkoorden vervangen
- Kranen watersmering schroefas vervangen ivm corrosie
- Borging kuiptafel herstellen
- Combi-magnetron vervangen
- Steun van intercooler lassen
- Niveaumeter brandstoftank vervangen
- Gangway platform icm carbon plank
- Trossensnijder nalopen
- Gelcoatschades kuip herstellen
- Generator extra startknop in kombuis
- Pianolampje voor eigenaarshut
- Achtergrondverlichting motordash checken
- Montageplaats watermakerpomp verwijderen van motorsteun
- Berijkbaar maken generator en groot onderhoud
- Revisie staart boegschroef
- CV thermostaat bereikbaar maken
- Salontafel nieuw
- Bakskistluiken schuren en coaten
- Irridium doorvoer verwijdren
- Spiegellampje SB eigenaar-bad vervangen
- Leeslampjes voor eigenaars hut
- SB Gasthut lamp vervangen


Henk Drijfhout
Bedrijfsleider - MYS
MEDEMBLIK YACHT SERVICE B.V.
Overleek 7, 1671 GD Medemblik
telefoon (0227) 54 36 22
fax (0227) 54 50 37