



BROKERAGE | CHARTER | BERTHS | FINANCE | INSURANCE | YACHT MANAGEMENT

#### **BROKER'S COMMENTS**

This well maintained Glacer 40 is a unique yacht model with a retractable keel, which is a standout feature for sailors looking for versatile draft options ideal for shallow waters and docking flexibility. This design allows for ease in both cruising and exploring coastal or shallow regions without sacrificing performance in deeper waters. Overall, this combination of a retractable keel and a stainless steel superstructure suggests the Glacer 40 is designed for both style and function, catering to sailors who prioritize versatility and low-maintenance resilience in their yacht's design.

Hans Visser

#### **SPECIFICATIONS**

Dimensions	12.00 x 3.80 x 1,10 / 2.20 (m)	Builder	CB Yachtbau
Built	1995	Cabins	3
Material	Steel	Berths	6
Engine(s)	1 x Ford Lehmann 2712E diesel	Hp/Kw	85.00 (hp), 62.56 (kw)
Asking price	€ 109.000 (VAT Paid)	Lying	contact Hindeloopen

#### CONTACT

Sales office	De Valk Hindeloopen B.V.	<b>Telephone</b> +31 514 52 40 00
Address	Oosterstrand 1	E-mail hindeloopen@devalk.nl
	8713 JS Hindeloopen	
	NL	

#### **DISCLAIMER**

These particulars are given in good faith as supplied but cannot be guaranteed.



Poland

#### **GENERAL**

Model **GLACER 40** Type sailing yacht

LOA (m) 12,00 Beam (m) 3,80 Draft (m) 2,20 Draft min (m) 1,10 Air draft (m) 17,00 Headroom (m) 1,90 Year built 1995

Builder CB Yachtbau Country

Designer Horst Glacer

Displacement (t) 15 CE norm NA Hull material steel Hull colour blue Hull thickness (mm) 5mm

Hull shape round-bilged Keel type centreboard Superstructure material stainless steel Rubbing strake stainless steel Deck material stainless steel Deck finish non-skid paint

Superstructure deck finish teak Cockpit deck finish teak

Antifouling (year) Hull underwater new system 2023 incl antifoul.

Dorades 2

Window frame aluminium Window material tempered glass

Deckhatch 2 x

**Portholes** yes

Insulation glasswool Fuel tank (litre) steel 1200

Level indicator (fuel tank) yes

Freshwater tank (litre) stainless steel 800

Level indicator (freshwater) yes

Blackwater tank (litre) steel 300 Blackwater tank extraction pump

Greywater tank (litre) See black water

Wheel steering hydraulic

Inside helm position yes

Outside helm position hydraulic

**Emergency tiller** yes

More info on paintwork Hull and deck repainted 2023

#### **ACCOMMODATION**

Cabins 3 **Berths** 6 Interior teak Layout yes Floor parquet Pilot house/deck saloon yes Headroom saloon (m)

Heating calorgas ducted hot air Trumatic, needs to be serviced..

1,90

**Navigation center** yes Chart table yes Aft Cabin yes

Galley L shaped Countertop corian

Sink stainless steel Cooker calor gas 3 burner



Oven yes
Fridge yes

Hot water system 220V + engine
Water pressure system electrical
Owners cabin v-bed

Bed length (m) 2.0

Wardrobe hanging and shelves

BathroomsharedToiletsharedToilet systemelectric

Wash basin in the bathroom

Shower shared
Guest cabin 1 double bed

Bed length (m) 2.0

Wardrobe hanging and shelves

Guest cabin 2 single bed

Bed length (m) 2.0

Wardrobe hanging and shelves

#### **MACHINERY**

No of engines 1

Make Ford Lehmann

Type 2712E HP 85 kW 62.56 Fuel diesel Year installed 1995 Maximum speed (kn) 7 Cruising speed (kn) 6 Consumption (I/hr) 3,5 **Engine hours** 1353



Engine cooling system closed keelcooling

Drive shaft Shaft seal Grease

**Engine controls** bowden cable Gearbox hydraulic Bowthruster electric **Exhaust** dry Propeller type fixed Propeller blades

Propeller shaft material stainless steel

**Shaft Iubrication** grease Manual bilge pump yes Electric bilge pump yes

Electrical installation 12 V DC and 220 V AC

Generator dry exhaust Fischer Panda

Running hours generator 185,7 **Batteries** 5 Start battery 1 Service battery 2 **Bowthruster battery** 2 **Battery monitor** yes

Battery charger Studer 6A Mastervolt Chargemaster 24/12-3 Mastervolt 12/25-3

Shorepower with cable

#### **NAVIGATION**

Compass Plastimo

Depth sounder Raytheon ST60

Log Raytheon ST 60 needs service Windset Raytheon ST 60 needs new topunit

VHF Sailor RT 2047

**Autopilot** Raytheon ST 6000+ Needs service



**GPS** yes

Navigation lights yes

#### **EQUIPMENT**

Sprayhood2 partsCockpit cover3 partsSun awningyesWinter coveryesCockpit tableTeakBathing platformSteel

Boarding ladder stainless steel

Deck shower yes

**Anchor** CQR Plough

Anchor chain yes

Windlass electrical Reckmann
Sea railing stainless steel Solid

Grab rail (superstructure)yesPushpityesPulpityesFendersyesMooring linesyesSpare partsSomeToolsSome

#### **RIGGING**

Rigging sloop
Standing rigging wire

Brand mast Reckmann
Material mast aluminium
Spreaders 2 sets

Mainsail Kary, dacron, has to be replaced.



Stoway mast Reckmann Hydraulic

Genoa Dacron, has to be replaced.

Genoa furler Reckmann

Gennaker yes
Booster yes
Stormjib yes

Reefing System main in-mast furling

Backstay adjuster yes

**Boomvang** gasspring

Primary sheet winch2 x Lewmar ST46 2spGenoa sheetwinches2 x Lewmar ST40 2sp

Halyard winches 2 x Lewmar ST on the mast

Multifunctional winches halyard/sheet winches 2 x Lewmar 16ST

Gennaker pole aluminium











































































































