



BROKERAGE | CHARTER | BERTHS | FINANCE | INSURANCE | YACHT MANAGEMENT

BROKER'S COMMENTS

This Glacer 40 is a unique yacht model with a retractable keel, which is a standout feature for sailors looking for versatile draft options ideal for shallow waters. This design allows for ease in both cruising and exploring coastal or shallow regions without sacrificing performance in deeper waters. This combination of a retractable keel and a stainless steel superstructure suggests the Glacer 40 is designed for both style and function. The Glacer 40 is being auctioned online, bidding is only possible through Bright Auctions. All auction information can be found at https://bit.ly/glacer40

Stein Dubbeldam

SPECIFICATIONS

Dimensions	12.00 x 3.80 x 2,20 / 1.10 (m)	Builder	CB Yachtbau
Built	1995	Cabins	3
Material	Steel	Berths	6
Engine(s)	1 x Ford Lehmann 2712E diesel	Hp/Kw	85.00 (hp), 62.56 (kw)
Asking price	€ 46.000 (VAT Paid)	Lying	at sales office

CONTACT

Sales office	De Valk Hindeloopen B.V.	Telephone	+31 514 52 40 00
Address	Oosterstrand 1	E-mail	hindeloopen@devalk.nl
	8713 JS Hindeloopen		
	NL		

DISCLAIMER

These particulars are given in good faith as supplied but cannot be guaranteed.



GENERAL

Model GLACER 40

Type sailing yacht

 LOA (m)
 12,00

 Beam (m)
 3,80

 Draft (m)
 1,10

 Draft min (m)
 2,20

 Air draft (m)
 17,00

 Headroom (m)
 1,90

 Year built
 1995

Builder CB Yachtbau

Country Poland

Designer Horst Glacer

Displacement (t) 15
CE norm NA
Hull material steel
Hull colour blue
Hull thickness (mm) 5mm

Hull shape round-bilged

Keel type centreboard One peace cast iron

Superstructure materialstainless steelRubbing strakestainless steelDeck materialstainless steelDeck finishnon-skid paint

Superstructure deck finish teak

Cockpit deck finish teak

Antifouling (year) Hull underwater new system 2023 incl antifoul.

Dorades 2

Window frame aluminium
Window material tempered glass

Deckhatch 2 x



Portholes yes

Insulation glasswool Fuel tank (litre) steel 1200

Level indicator (fuel tank) yes

Freshwater tank (litre) stainless steel 800

Level indicator (freshwater) yes

Blackwater tank (litre) steel 300 Blackwater tank extraction pump

Greywater tank (litre) See black water

Wheel steering hydraulic

Inside helm position yes

Outside helm position hydraulic

Emergency tiller yes

More info on paintwork Hull and deck repainted 2023

ACCOMMODATION

Cabins 3 **Berths** 6 Interior teak Layout yes Floor parquet Pilot house/deck saloon yes Headroom saloon (m)

Heating calorgas ducted hot air | Trumatic | needs service

1,90

Navigation center yes Chart table yes Aft Cabin yes

Galley L shaped Countertop corian

Sink stainless steel Cooker calor gas 3 burner



Oven yes

Hot water system 220V + engine | pressure relief valve needs to be replaced

Water pressure system electrical

Owners cabin v-bed

Bed length (m) 2.0

Wardrobe hanging and shelves

BathroomsharedToiletsharedToilet systemelectric

Wash basin in the bathroom

Shower shared
Guest cabin 1 double bed

Bed length (m) 2.0

Wardrobe hanging and shelves

Guest cabin 2 single bed

Bed length (m) 2.0

Wardrobe hanging and shelves

MACHINERY

No of engines

Make Ford Lehmann

Type 2712E HP 85 kW 62.56 Fuel diesel Year installed 1995 Maximum speed (kn) 7 Cruising speed (kn) 6 Consumption (I/hr) 3,5 **Engine hours** 1353

Engine cooling system closed keelcooling



Drive shaft
Shaft seal Grease

Engine controlsbowden cableGearboxhydraulicBowthrusterelectric

Exhaust dry | is rusty

Propeller type fixed
Propeller blades 3

Propeller shaft material stainless steel

Shaft lubrication grease
Manual bilge pump yes

Electrical installation 12 V DC and 220 V AC

Generator Fischer Panda 4000s.Neo PMS | 3,4 KW | Fresh water pump

defect

Running hours generator 185,7

Batteries 5

Start battery 1

Service battery 2

Bowthruster battery 2

Battery monitor yes

Battery charger Studer 6A Mastervolt Chargemaster 24/12-3 Mastervolt 12/25-3

Shorepower with cable

NAVIGATION

Compass Plastimo

Depth sounder Raytheon ST60

Log Raytheon ST 60 needs service
Windset Raytheon ST 60 needs new topunit

VHF Sailor RT 2047

Autopilot Raytheon ST 6000+ Needs service

GPS yes



Navigation lights yes

EQUIPMENT

Sprayhood2 partsCockpit cover3 partsSun awningyesWinter coveryesCockpit tableTeakBathing platformSteel

Boarding ladder stainless steel
Anchor CQR Plough

Anchor chain yes

Windlass electrical Reckmann
Sea railing stainless steel Solid

Grab rail (superstructure)yesPushpityesPulpityesFendersyesMooring linesyesSpare partsSomeToolsSome

RIGGING

Rigging sloop
Standing rigging wire

Brand mastReckmannMaterial mastaluminiumSpreaders2 sets

Mainsail Kary, dacron, has to be replaced.

Stoway mast Reckmann Hydraulic

Genoa Dacron, has to be replaced.



Genoa furler Reckmann

Gennaker yes Stormjib yes

Reefing System main in-mast furling

Backstay adjuster yes

Boomvang gasspring

Primary sheet winch2 x Lewmar ST46 2spGenoa sheetwinches2 x Lewmar ST40 2sp

Halyard winches 2 x Lewmar ST on the mast

Multifunctional winches halyard/sheet winches 2 x Lewmar 16ST

Gennaker pole aluminium











































































































