





BROKERAGE | CHARTER | BERTHS | FINANCE | INSURANCE | YACHT MANAGEMENT

#### **BROKER'S COMMENTS**

Classified as "Yacht of the Year 1992", the Dehler 43 CWS has long been the flagship of Dehler from Germany. With lots of innovations, Dehler cornered the market for fast and safe cruisingyachts from the seventies onwards. They set standards for yachtbuilding that are still valid to this day. The Dehler 43 CWS is a true "short handed" sailingyacht. This boat needs a refit. Please contact us for more information.

Jan-Ward van Dantzig

#### **SPECIFICATIONS**

Dimensions	13.20 x 3.95 x 2.00 (m)	Builder	Dehler Yachtbau GmbH
Built	1995	Cabins	3
Material	GRP	Berths	8
Engine(s)	1 x Yanmar 4JH-2BE diesel	Hp/Kw	48.00 (hp), 35.28 (kw)
Asking price	sold (VAT )	Lying	at sales office

#### CONTACT

Sales office	De Valk Sint Annaland B.V.	<b>Telephone</b> +31 (0)166 601 000
Address	Koelhuisweg 4	E-mail sintannaland@devalk.nl
	4697 RM Sint Annaland	
	NL	

#### **DISCLAIMER**

These particulars are given in good faith as supplied but cannot be guaranteed.



#### **GENERAL**

Model DEHLER 43 CWS

Type sailing yacht

LOA (m) 13,20 LWL (m) 11,60 Beam (m) 3,95 Draft (m) 2,00 Air draft (m) 19,40 Headroom (m) 1,90 Year built 1995 Launched 1996

Builder Dehler Yachtbau GmbH

**Country** Germany

**Designer** Van de Stadt & Partners

Displacement (t) 8,7

Ballast (tonnes) 3,7

CE norm NA

Hull material GRP

Hull colour grey

Hull shaperound-bilgedKeel typefin keelSuperstructure materialGRP

Rubbing strake rubber

Deck material GRP Balsa

Deck materialGRP Balsa SandwichDeck finishTBS non-skid profile mats

Superstructure deck finish non-skid moulded in

Cockpit deck finish teak (in bad condition) on seats & teak grating on the cockpit

floor

Antifouling (year) 2022

**Dorades** 2 x plastic

Window frame aluminium Lewmar (with rollo's)

Window material polycarbonate



DeckhatchLewmarPortholesyes

Insulation Balsa Sandwich
Fuel tank (litre) steel 250

Level indicator (fuel tank)(not functioning)Freshwater tank (litre)polyethylene 330Level indicator (freshwater)(not functioning)Blackwater tank (litre)polyethylene 25

Wheel steering 2 x stainless steel Solimar steering wheel

Emergency tiller yes

More info on hull Polyester / Kevlar / Balsa Sandwich

Extra info Balanced spade rudder with a new bearing (2018)

#### **ACCOMMODATION**

Cabins 3
Berths 8

Interior mahogany With light grey leather upholstery

Floor teak and holly

Saloon yes
Headroom saloon (m) 1,90

**Heating** diesel ducted hot air Webasto

Chart table Infront of the entrance

Dinette to convert into berth yes

Galley On port side (headroom: 1,97 m)

**Countertop** plastic

Sinkstainless steel 2 xCookercalor gas 3 burner

**Oven** yes

Fridge Top loader with a compressor

Hot water system 220V + engine 1 x 25 liter Isotemp + 1 x 45 liter Isotemp (is

leaking)



Water pressure system electrical

**Crockery** yes

Owners cabin double bed (in the front cabin - headroom 1,86 m)

**Bed length (m)** 1,97 x 1,85

Wardrobe hanging and shelves

Bathroom en suite (headroom 1,92 m)

**Toilet** en suite

Toilet system manual PAR (pump needs to be replaced)

Wash basin in the bathroom Stainless steel

Bath tub en suite Under bed in the front cabin (with hot and cold water)

Guest cabin 1 double bed (aft cabin port side - headroom 1,95 m)

Bed length (m) 2,00 x 1,45

Wardrobe hanging and shelves

Bathroom shared (headroom 1,95 m)

**Toilet** shared

Toilet system manual PAR (pump needs to be replaced)

Wash basin in the bathroom Stainless steel

Shower en suite (seperated in the aft bathroom - headroom 1,97 m)

Guest cabin 2 double bed (aft cabin starboard side - headroom 1,95 m)

Bed length (m) 2,00 x 1,45

Wardrobe hanging and shelves

#### **MACHINERY**

No of engines 1

Make Yanmar
Type 4JH-2BE

HP 48
kW 35.28
Fuel diesel
Year installed 1995

Maximum speed (kn) 8



 Cruising speed (kn)
 7

 Consumption (I/hr)
 2,8

 Engine hours
 1132

Engine cooling system freshwater heat exchanger

**Drive** shaft

Engine controls bowden cable 2 x

Gearbox mechanical Exhaust watercooled

Propeller type fixed
Propeller blades 3

Propeller shaft material stainless steel

Manual bilge pump yes
Electric bilge pump yes

Electrical installation 12 + 220 Volt
Start battery 1 x 72 Ah (2022)

Service battery

3 x ca. 220 Ah (need to be renewed)

Battery monitor

Mastervolt Combi System Control Panel

Battery charger/inverter

Mastervolt Combi 12 Volt / 2.400 Watt

1 x with Jota Teca Solarix inverter

Diode battery combiners yes

Shorepower with cable

Extra info Mastervolt alternator 150 A

Extra info Bowtruster engine has been removed, bowtruster pipe is present

#### **NAVIGATION**

Compass 2 x Suunto (fluid is missing)

Electric compassRobertson Dataline Compass (not functioning)Depth sounderRobertson Dataline Depht (not functioning)LogRobertson Dataline Speed (not functioning)

Windset Robertson Dataline Wind & Wind+ (not functioning)

Repeater Robertson Dataline Central (not functioning)



VHF Shipman RS 8300 (not functioning)

Autopilot Autohelm ST6000

Radar 1 x Raytheon R40XX & 1 x Raytheon R10 (inside - not

functioning)

GPS Furuno GPS/WAAS GP-32 (2004) Plotter Yeoman (old - functioning unknown)

Navtex Nav4 Navtex (not functioning) Radio receiver HF-150 (functioning unknown)

**Navigation lights** 

Loudhailer Raytheon Ray 430 Loudhailer (functioning unknown)

Extra info Robertson Dataline Waypoint+ (not functioning)

**EQUIPMENT** 

Fixed windscreen Perspex (center window needs to be replaced)

Sprayhood (needs to be replaced)

Winter cover Over complete boat (with standing mast)

Cockpit table Teak (removable and turnable) **Bathing platform** Manual lowering, aplied with teak

**Boarding ladder** stainless steel Integrated in bating platform

Deck shower Hot and cold (is leaking) Anchor Delta Galvanished Anchor chain Chain and rope Windlass

**Outboard support** On pushpit

Sea railing wire (double wired)

Grab rail (superstructure) aluminium Railing side opening gates On both sides **Pushpit** Stainless steel **Pulpit** Stainless steel

Life raft container Plastimo (1996)

Life raft (pers) 6

electrical Lewmar

Last life raft survey 2001 (needs to be surveyed)

**Lifejackets** 7 x orange

Lifebuoy 1 x

Danbuoy Joon

Safety lines on deck 2 x Strap

Clearview window (functioning unknown)

Radar reflector 2 x

**Fenders** 8 x new black fender and 6 x white fender

Mooring lines yes
Tools yes

Radio-cd player Sony radio/cd-charger (10 Discs)

Cockpit speakers 2 x

Speakers in salon 2 x Blauwpunkt

Clock - barometer yes
Fire extinguisher 3 x

Latest extinguisher survey

Need to be surveyed or replaced

Extra info 1 x folding mast-step

#### **RIGGING**

Rigging fractional
Standing rigging wire

Brand mast Dehler
Material mast aluminium
Spreaders 2 x 2

Mainsail cover Dehler Maindrop cover with Lazy-Jacks (1998)

**Battcars** Frederiksen

Fully battened mainsail North Sails : Dacron mainsail (old)

Jib North Sails: 105% Furling Jib - Soft Norlam (2003)

Genoa North Sails: Furling Genoa (old)

Genoa furler yes
Genoa cover White



Gennaker North Sails: 165% Easymidi Gennaker (2002 - as new) with

Snuffer

**Spinnaker** Old spinnaker with a snuffer

Reefing System slabreefing

Boomvang tackle (Rope needs to be replaced)

Boomvang mechanical Rigged Easy Kicker

Primary sheet winch 2 x Harken 46 ST (electric)

Genoa sheetwinches2 x Harken 42 STHalyard winches1 x Lewmar 30 STSpi-polealuminium Selden

Extra info Sails not used/mounted since 2005. Running rig needs

replacement

Extra info 12 x Spinlock jammer in cockpit and 5x outside cockpit

































































































































