



BROKERAGE | CHARTER | BERTHS | FINANCE | INSURANCE | YACHT MANAGEMENT

BROKER'S COMMENTS

This Brandsma Noordzeekotter 1400 has been well maintained by the current and previous owner. The ship has very spacious decks, gangways and a unique seating area on the aft deck. The Nelson has two beautiful cabins with a French bed each and full bathrooms with toilet and shower. The galley and dinette are located under the huge aft deck with the large owner's cabin behind it. She can be visited in our sales marina in Loosdrecht.

Mark Hesselmans

SPECIFICATIONS

| Dimensions | 14.00 x 4.30 x 1.25 (m) | Builder | Brandsma Sneek |
|--------------|------------------------------|---------|-------------------------|
| Built | 1992 | Cabins | 2 |
| Material | Steel | Berths | 6 |
| Engine(s) | 1 x Ford Lehman SP135 diesel | Hp/Kw | 135.00 (hp), 99.22 (kw) |
| Asking price | sold (VAT) | Lying | at sales office |
| | | | |

CONTACT

| Sales office | De Valk Loosdrecht B.V. | Telephone | +31 (0)35 582 90 30 |
|--------------|--------------------------------|-----------|----------------------|
| Address | 't Breukeleveense Meentje 6 | E-mail | loosdrecht@devalk.nl |
| | 1231LM Loosdrecht / Wijdemeren | | |
| | NL | | |
| | | | |

DISCLAIMER

These particulars are given in good faith as supplied but cannot be guaranteed.



1992

GENERAL

Model **BRANDSMA NOORDZEEKOTTER 1400**

Type motor yacht

LOA (m) 14,00 Beam (m) 4,30 Draft (m) 1,25 Air draft (m) 3,00 Headroom (m) 2,00 Year built

Builder Brandsma Sneek Country The Netherlands

Designer Brandsma

Displacement (t) 20 CE norm NA Hull material steel Hull colour grey

Hull shape multi hard chine

Keel type long keel Superstructure material steel Deck material steel Deck finish teak Cockpit deck finish teak

Antifouling (year) 2021 hull polished

Window frame aluminium Window material double glazing **Portholes** aluminium Radar arch collapsible Fuel tank (litre) steel 1000 +/-

Level indicator (fuel tank) yes

Freshwater tank (litre) steel 2x 500 +/-Blackwater tank (litre) steel 100 +/-



Wheel steering hydraulic

Outside helm position hydraulic

ACCOMMODATION

 Cabins
 2

 Berths
 6

 Interior
 teak

 Floor
 carpet

 Aft deck
 yes

 Saloon
 yes

 Headroom saloon (m)
 2+/

Heating diesel ducted hot air Eberspracher D4
Heating 2 diesel ducted hot air Eberspracher D4

Aft Cabin yes

Dinette to convert into berth yes

Opening door to aft deck yes

Galley yes

Countertop plastic

Sink

Cooker calor gas
Microwave/oven combi 2020

Fridge2X with freezerHot water system220V + engineWater pressure systemBoiler 2020

Owners cabinFrench bed Matras 2020Wardrobehanging/drawers/shelves

Bathroomen suiteToileten suiteToilet systemelectric

Wash basin in the bathroom

Shower en suite



Guest cabin 1 French bed

Wardrobe hanging/drawers/shelves

Bathroom en suite **Toilet** en suite Toilet system electric

Wash basin in the bathroom

Shower en suite Washing machine Aftcabin

MACHINERY

No of engines

Make Ford Lehman

Type SP135 HP 135 kW 99,22 Fuel diesel Year installed 1992 Maximum speed (kn) 7,5 Cruising speed (kn) 6 **Engine hours**

Engine cooling system freshwater heat exchanger

4450

Drive shaft

Engine controls bowden cable Gearbox hydraulic Velvet

Bowthruster electric

Sternthruster electric 2020 Quick

Exhaust

Propeller type fixed

Propeller shaft material stainless steel Shaft lubrication grease Automatic

Manual bilge pump yes



Electric bilge pump yes

Generator wet exhaust Fisher Panda 4 kva

Running hours generator 225

Batteries 4x 200 Amp 2020

Start battery2x 2020Battery chargerMastervoltBattery charger/inverterVictron

Solar panel Fox-220 2015
Shorepower with cable

NAVIGATION

CompassyesLogyesVHFyes

Autopilot Simrad AP21

Plotter Garmin
Plotter/GPS yes

EQUIPMENT

Cockpit cover yes

Dodger yes

Sun awning yes

Cockpit cushions yes

Cockpit table yes

Cockpit chairs yes

Bathing platform yes

Boarding ladder stainless steel

Transom door yes

Deck shower Hot and cold water

Anchor

Anchor chain yes



Windlass electrical
Sea railing teak

Wiper yes

Horn

TV 2020 Samsung

Radio-cd player Defect



































































































































